



Chambersburg FD

Job #39589

THIS REPORT CONTAINS PHOTOS OF:

- The pump house structure.
- The pump with valves.
- The pump mounted in the pump house.
- The parts for rear body weld.



GLICK

FIRE EQUIPMENT COMPANY, INC.

















