



Chambersburg FD
Job #39589

THIS REPORT CONTAINS PHOTOS OF:

- The start of the cab weld.
- The pump arrival.



GLICK

FIRE EQUIPMENT COMPANY, INC.









