



Alpha FC
Job #39840

THIS REPORT CONTAINS PHOTOS OF:

- The cab in the paint process.
- The beginning of the body build.
- The pump with the valves installed.



GLICK
FIRE EQUIPMENT COMPANY, INC.













