



Alpha FC
Job #39840

THIS REPORT CONTAINS PHOTOS OF:

- The cab in the paint process.
- The body build completed.
- The pump mounted in the pump house structure.
- The frame rail arrival.



GLICK
FIRE EQUIPMENT COMPANY, INC.

























