



Edgely FC
Job #40186

THIS REPORT CONTAINS PHOTOS OF:

- The torque box now inside and assembly work has begun.
- The chassis awaiting future torque box mount.



GLICK
FIRE EQUIPMENT COMPANY, INC.





















