



Edgely FC
Job #40186

THIS REPORT CONTAINS PHOTOS OF:

- The torque box before it is mounted.
- The torque box now mounted on the chassis.



GLICK
FIRE EQUIPMENT COMPANY, INC.

































