




Edgely FC
Job #40186

THIS REPORT CONTAINS PHOTOS OF:

- The cab now mounted to the chassis.
- The torque box arrival.



GLICK

FIRE EQUIPMENT COMPANY, INC.









