




Shaler Villa VFC

Job #40364

THIS REPORT CONTAINS PHOTOS OF:

- The chassis with the front body section mounted.
- The rear body being prepped for future mounting on the chassis.
- The ladder arrival.



GLICK

FIRE EQUIPMENT COMPANY, INC.











