




Shaler Villa VFC

Job #40364

THIS REPORT CONTAINS PHOTOS OF:

- The cab painted.
- The body build process.
- The front body section.



GLICK

FIRE EQUIPMENT COMPANY, INC.



