




Shaler Villa VFC

Job #40364

THIS REPORT CONTAINS PHOTOS OF:

- The rear body now on the chassis and assembly line work in progress.
- The ladder assembly progress.



GLICK

FIRE EQUIPMENT COMPANY, INC.









