



Shaler Villa VFC

Job #40364

THIS REPORT CONTAINS PHOTOS OF:

- The PUC pump manifold now mounted in the front body section.
- The front bumper extension.
- The water tank.

GLICK

FIRE EQUIPMENT COMPANY, INC.













