



Wissahickon FC

Job #40664

THIS REPORT CONTAINS PHOTOS OF:

- The chassis before and after the cab mounted.
- The rear body in the paint process.
- The front body with the PUC manifold installed.
- The torque box assembly progress.



GLICK

FIRE EQUIPMENT COMPANY, INC.











































































