



Norristown FD

Job #41019

THIS REPORT CONTAINS PHOTOS OF:

- The chassis now at the assembly plant and staged for future tiller bay work.
- The rear body section painted.
- The torque box arrival.



GLICK

FIRE EQUIPMENT COMPANY, INC.













































