



Laurel FC
Job #44994

THIS REPORT CONTAINS PHOTOS OF:

- The cab in the paint process.
- The completed body.
- The pump mounted in the pump house structure.
- The frame rail arrival.



GLICK
FIRE EQUIPMENT COMPANY, INC.

























