



Falls Twp FC

Job #39629

THIS REPORT CONTAINS PHOTOS OF:

- The torque box now mounted to the chassis.
- The body assembly line progress.



GLICK

FIRE EQUIPMENT COMPANY, INC.









































