

East Allen Twp

Job #40363


THIS REPORT CONTAINS PHOTOS OF:


- The truck as testing and assembly continue.

GLICK

FIRE EQUIPMENT COMPANY, INC.


Pierce
45












40363


40363
40363


PULL TO OPEN
MANIFOLD DRAIN
PULL TO OPEN
DRIVER SIDE
AUXILIARY INLET


FOAM
MANIFOLD DRAIN
FOAM
MANIFOLD DRAIN
FOAM PUMP
INTAKE DRAIN
FOAM PUMP
DISCHARGE DRAIN
PULL TO OPEN
FOAM TANK DRAIN








40363


40363


40363


SHORTAGE






PULL TO OPEN
LARGE DIAMETER
DISCHARGE REAR
Pierce




Pierce














40363


PULL TO OPEN
FRONT INLET





DO NOT CAP
Pierce


PULL TO OPEN
FRONT INLET








5