



Norristown FD

Job #41019

THIS REPORT CONTAINS PHOTOS OF:

- The cab with interior.
- The body build progress.
- The rear tractor platform.



GLICK


FIRE EQUIPMENT COMPANY, INC.



















WARNING DO NOT REMOVE
SPARE WIRING BEHIND PANEL

OPTION # _____
WIRE # Tiller Steer Display
TERMINATION TYPE _____
TERM LOC. _____
VERIFICATION CLOCK # _____ 1663539

WARNING DO NOT REMOVE
SPARE WIRING BEHIND PANEL

OPTION # 0636439
WIRE # 8123, 8124, 8127
TERMINATION TYPE Shrink B's
TERM LOC. Dash
VERIFICATION CLOCK # 265414 1663539

WARNING DO NOT REMOVE
SPARE WIRING BEHIND PANEL

OPTION # _____
WIRE # ANTX3
TERMINATION TYPE _____
TERM LOC. _____
VERIFICATION CLOCK # _____ 1663539

WARNING DO NOT REMOVE
SPARE WIRING BEHIND PANEL

OPTION # 0636439
WIRE # 2122, 8122, 8121
TERMINATION TYPE Shrink B's
TERM LOC. Dash
VERIFICATION CLOCK # 265414 1663539







