





Carnegie Volunteer Fire and Rescue 41876

Work continues on your Saber pumper. This week post paint assembly of the pumphouse was completed and the pumphouse underwent a hydrostatic test to verify no leaks within the pump or plumbing. The pumphouse was then mounted onto the chassis.



GLICK

FIRE EQUIPMENT COMPANY, INC.



