

Twp of Haverford

Job #42069

THIS REPORT CONTAINS PHOTOS OF:

- The truck with graphics in checkout for final assembly as it gets closer to final inspection.

GLICK

FIRE EQUIPMENT COMPANY, INC.


HENDERSONVIL
FIRE DEPT.
DENTON
FIRE DEPT
BON AIR
Pierce
E 58


BON AIR
Pierce
BON AIR
58
HAVERFORD TWP
BUREAU OF FIRE


BON AIR
58
FIRE CO.
HAVERFORD TWP.
BUREAU OF FIRE


BON AIR
BON AIR
58
FIRE CO.


HAVERFORD TWP.
BUREAU OF FIRE
BON AIR
SINCE 1918
FIRE CO


BON AIR
4
HT BF
1918




VERFORD TWP.
UREAU OF FIRE






H·T·B·F
ENGINE
58
SALUTE THOSE WHO SERVE


H·T·B·F
ENGINE
58
Pierce
DYNATECT
AMDOR


H·T·B·F


9-11-01
IN MEMORY OF OUR FALLEN BROTHERS












HAVERFORD TWP.
BUREAU OF FIRE


HAVERFORD TWP.
BUREAU OF FIRE
BON AIR
58








CAUTION
ULTRA LOW SULFUR
DIESEL FUEL ONLY!
Filling the fuel tank with other liquids can result in premature failure of engine and emissions components.






BON AIR
58
BON AIR


ERSONVILLE
FIRE DEPT.




Pierce
CERTIFIED
CLEAN IDLE


ST. BERNARD













Pierce


PROTECT ALL OPENING
SEALER
REMOVE BEFORE SHIPPING












Pierce
KENWOOD

