




Montgomery Twp
Job #39747

THIS REPORT CONTAINS PHOTOS OF:

- The truck as assembly line work continues.
- The pump panels close up.



GLICK
FIRE EQUIPMENT COMPANY, INC.
















































CAUTION
ENSURE FRONT
INLET SWIVEL
IS FACING
FORWARD BEFORE
RAISING CAB

