




**Harmony FD**

**Job #40288**

**THIS REPORT CONTAINS PHOTOS OF:**

- The cab with interior progress.
- The body in the prime and paint process.
- The pump house done and staged for future mount.



**GLICK**

**FIRE EQUIPMENT COMPANY, INC.**









STOP "ECK" STOP

**CORROSION PREVENTION TREATMENT FOR DISSIMILAR METALS**

When dissimilar sheet metals are joined together with a threaded fastener, a corrosion preventive Eckip, will be applied to either the fastener or hole location. This will be applied to both cast body sheet metal.









