




Lower Moreland Township
41630

Work continues on your Saber Pumper. The engine and transmission have been installed in the chassis. Diamond plate trim, lights, handrails and electrical harness are being installed in the rear body. Post paint assembly is complete on the water pump and is undergoing a hydrostatic leak test.



GLICK
FIRE EQUIPMENT COMPANY, INC.























