



Edgely FC
Job #40186

THIS REPORT CONTAINS PHOTOS OF:

- The cab with interior.
- The chassis with tires and the VIN.
- The body in the paint process.



GLICK
FIRE EQUIPMENT COMPANY, INC.





































































