




**Barlow VFC**  
**Job #40253**

**THIS REPORT CONTAINS PHOTOS OF:**

- The cab now painted and assembly has begun.
- The chassis prior to paint with the VIN.
- The body in the build process.
- The pump with valves installed.



**GLICK**  
**FIRE EQUIPMENT COMPANY, INC.**









