



Whitpain Twp
Job #40287

THIS REPORT CONTAINS PHOTOS OF:

- The cab with interior.
- The body painted.
- The front bumper assembly.



GLICK
FIRE EQUIPMENT COMPANY, INC.






































WARNING DO NOT REMOVE
SPARE WIRING BEHIND PANEL
OPTION # *Officer Side Speedometer*
WIRE # *A125N - A163N - A169N*
TERMINATION TYPE *Shrinkables*
TERM LOC. *Dash*
VERIFICATION CLOCK # *292546*
1663539

WARNING DO NOT REMOVE
SPARE WIRING BEHIND PANEL
OPTION # *0696437 (2)*
WIRE # *Antenna*
TERMINATION TYPE *2-WAY*
TERM LOC. *DASH*
VERIFICATION CLOCK # *292546*
1663539













