




Harmony FD

Job #40288

THIS REPORT CONTAINS PHOTOS OF:

- The cab in primer and staged for future paint.
- The start of the body panels.
- The pump house structure.
- The pump with the valves installed.
- The frame rail arrival.
- The VIN.



GLICK

FIRE EQUIPMENT COMPANY, INC.



























