




**Harmony FD**

**Job #40288**

**THIS REPORT CONTAINS PHOTOS OF:**

- The cab painted and in the quality booth.
- The pump mounted in the pump house.
- The beginning of the body build.



**GLICK**

**FIRE EQUIPMENT COMPANY, INC.**







