




Harmony FD

Job #40288

THIS REPORT CONTAINS PHOTOS OF:

- The pump house progress.
- The finished body which will be staged for future metal finish and paint.
- The chassis build progress.



GLICK

FIRE EQUIPMENT COMPANY, INC.





