




Harmony FD

Job #40288

THIS REPORT CONTAINS PHOTOS OF:

- The cab back from lineax and on the cab assembly line.
- The pump house finished and staged for future metal finish and paint.
- The completed chassis build.



GLICK

FIRE EQUIPMENT COMPANY, INC.





