




Shaler Villa VFC

Job #40364

THIS REPORT CONTAINS PHOTOS OF:

- The truck assembly line work continues.
- The interior pump panel close up.



GLICK

FIRE EQUIPMENT COMPANY, INC.







