



Granville Fire Company

40900

Work continues on your Freightliner pumper. The cab and chassis continue on the chassis assembly line. Paint work is nearly complete on the pump house. The rear body has had chevron graphics installed and is in the body assembly area where lights, electrical harnesses and compartment doors are installed.

GLICK

FIRE EQUIPMENT COMPANY, INC.

















