



Granville Fire Company

40900

Work continues on your Freightliner Tanker.
Paint is complete on the chassis and is ready
for reassembly.



GLICK

FIRE EQUIPMENT COMPANY, INC.









