Radnor FC

Job #40965

THIS REPORT CONTAINS PHOTOS OF:

- The cab and pump house painted.
- The chassis with tires and the VIN.

GLICK

FIRE EQUIPMENT COMPANY, INC.



BODY QUEUE QTY 1

Hold 4 Blast

40965

40965









6



385/65 R 22.5

11R 22.5

4P1BCAGF8TA030384