



Reading Fire Department

42055

Work continues on your Freightliner pumper. This week the cab and chassis were painted and post paint reassembly has begun. The rear body was assembled and is ready to start the paint process.



GLICK

FIRE EQUIPMENT COMPANY, INC.















