

Twp of Lower Merion

Job #42868

THIS REPORT CONTAINS PHOTOS OF:

- The chassis with some cab interior.
- The torque box now inside and assembly has begun.
- The reservoir compartment painted.

GLICK

FIRE EQUIPMENT COMPANY, INC.






Pierce




G751 MSA
GOODYEAR






GOODYEAR
STEEL MSA


GOODYEAR
G751 MSA





















SRS


SRS


Pierce


Pierce
Pierce
Pierce






























Rag
ATM
Clean
Rags












X 42868





