



Reading DFRS
Job #42053

THIS REPORT CONTAINS PHOTOS OF:

- The cab with interior.
- The body progress.
- The tillerman cab built and painted.
- The tractor rear platform.
- The torque box arrival.



GLICK


FIRE EQUIPMENT COMPANY, INC.























WARNING DO NOT REMOVE
SPARE WIRING BEHIND PANEL

OPTION # 2696439(x3)
WIRE # _____
TERMINATION TYPE Antenna
TERM LOC. Ip area
VERIFICATION CLOCK # 290512
1663539

