



## Reading DFRS

Job #42208

### THIS REPORT CONTAINS PHOTOS OF:

- The cab with interior progress.
- The rear body section metal finished.
- The front tank section progress.
- The tractor rear platform.



# GLICK


FIRE EQUIPMENT COMPANY, INC.



















**WARNING DO NOT REMOVE  
SPARE WIRING BEHIND PANEL**  
OPTION # 548004  
WIRE # 8003 1640  
TERMINATION TYPE Shrink B's  
TERM LOC. Loc 14  
VERIFICATION CLOCK # 273048  
1663539

**WARNING DO NOT REMOVE  
SPARE WIRING BEHIND PANEL**  
OPTION # \_\_\_\_\_  
WIRE # ANT X3  
TERMINATION TYPE \_\_\_\_\_  
TERM LOC. Dash  
VERIFICATION CLOCK # \_\_\_\_\_  
1663539





















