



**Cocalico Area Fire Department**  
**42362**

Work continues on your Saber pumper. This week the cab has started post paint assembly. The body completed post paint assembly which included installation of lights, wire harnesses, and compartment doors. The chassis has started on the chassis assembly line including installation of the engine and transmission.



**GLICK**  
**FIRE EQUIPMENT COMPANY, INC.**





























