



Lyons Volunteer Fire Company

42700

Work continues on your Kenworth Tanker. The chevron has been installed on the rear of the water tank. The rear body has been painted. The plumbing is complete and the pump will be painted before pump panels and gauges are installed.



GLICK

FIRE EQUIPMENT COMPANY, INC.

















