



Rheems FFC

Job #40663

THIS REPORT CONTAINS PHOTOS OF:

- The cab in the paint process.
- The pump house progress.
- The body finished and staged for future metal finish and paint.



GLICK

FIRE EQUIPMENT COMPANY, INC.



















