



Somerset Regional VFD

43041

Work continues on your Kenworth Tanker. Paint has started on the body. The water tank is in the paint shop and unavailable for pictures. Installation of the water pump and plumbing has started in the pumphouse.



GLICK

FIRE EQUIPMENT COMPANY, INC.













