



Somerset Regional VFD
43041

Work continues on your Kenworth Tanker. The chassis continues down the chassis assembly line. Installation of is nearly complete of the pump and will be going to the test area for a hydrostatic test.



GLICK

FIRE EQUIPMENT COMPANY, INC.



















