



Valley Regional Fire & Rescue

44384

Work continues on your Saber Pumper. This week the cab has completed the paint process. The pump has completed post paint assembly and will be leak tested in the test facility.



GLICK

FIRE EQUIPMENT COMPANY, INC.















